

BCA BE Seminar 2022
Buildings: What Can Go Wrong

Lessons Learnt from Structural Failures

Er Santoso Lukito

Senior Engineer/Construction and Structural Investigation Department

Building and Construction Authority

Overview of Structural Failure

Past failure serves as a reminder for industry practitioners to give due consideration on design and construction with building safety in mind throughout the project life-cycle and beyond.

- Wide array of available digital tools and over-reliance of engineering software have resulted in shorter design period and reduced manpower.
- Increasingly complex structure coupled with advancement in construction technology introduce additional risks and uncertainties in design/construction.

BUILDINGS: WHAT CAN GO WRONG



Contents

- Overview of structural failure
- Lesson learnt
 - Multi-purpose hall roof collapse
 - Cracks in tree-shaped column
 - Post-installed anchor failure
 - Cantilever member collapse
 - Party wall collapse
- Guides to improve safety
- Closing remarks


Lesson Learnt

Multi-purpose hall roof collapse

4 storey multi-purpose hall with a pitched roof truss supported by RC column, spanning over 27m. The roof collapsed onto the 2nd storey while under construction.

Key triggering factor:

- Inadequate design of the RC column support. Interactions of trusses with the supporting column were not considered.
- The joint support was assumed to be roller-support in the design while fixed bolted connection was provided on site. Outward horizontal forces arising from arching actions of inverted V-shaped truss were transmitted to the column.





Lesson Learnt

Multi-purpose hall roof collapse

- Column was orientated with weaker axes resisting the lateral thrust from the truss. Additional moment due to slenderness were also not considered in the design.

Lesson learnt:

- Interactions of roof trusses with supporting columns and the orientation to resist the lateral thrust should be studied and analysed carefully.
- Connection details to be adequately provided in the drawing to prevent erroneous construction.




Lesson Learnt

Cracks in tree-shaped column


Cracks observed on the column top, side and bearing support of multi-storey building during construction.

Key triggering factor:


- Thick concrete cover, high stress concentration and ineffective transfer of anchorage force.
- Overlooked detailing issues. Omission of links in the upper part of column that provides restraining force to tie the top of column together so as to prevent the 4 inclined members to act as independent cantilevers.



High stress concentration & ineffective transfer



Thick cover – 400mm





Lesson Learnt

Cracks in tree-shaped column

- Remedial proposal for the column cracks involved casting the 4 inclined members into a single plate and enlarging of the vertical portion of the columns.
- It created a more direct load transfer path in the column to avoid the original path which relied on the provision of the missing links.

Lesson learnt:

- Rebar detailing is critical in areas of high concentration of tension, bending and shear forces.



Lesson Learnt

Post-installed anchor failure

Roof canopy supported by a series of 5m span cantilever trusses collapsed due to joint failure. The cantilever structure broke off from the existing building, debonding the anchors from the supporting RC member.

Key triggering factor:

- Actual anchorage length observed was only half of what it was designed for. The anchors were mostly embedded in plaster.

Lesson learnt:

- Inadequate embedment may result in significant reduction in shear and tension capacity of the anchors that eventually led to a failure at the connections.



Lesson Learnt

Cantilever member collapse



Cantilever steel canopy serving as a bus bay shelter collapsed at column joint.

Key triggering factor:

- Splice plate was adopted to allow for different column size at lower and upper section. Fillet weld was carried out on site instead of the full penetration butt weld.

Lesson learnt:

- Inadequate joint connection to resist the overturning force in the column may lead to failure.



Lesson Learnt

Cantilever member collapse

6th storey cantilever concrete slab collapsed and triggered progressive collapse of the 2nd to 5th storey corridor slab.

Key triggering factor:

- Inadequate provision of bars observed. Reinforcement 50% less than shown in the drawings.
- Lack of inspection where the rebar rust due to water seepage along the corridor. Sign of corrosion further weakened the cantilevered slab.





Lesson Learnt

Cantilever member collapse

3m long cantilever car porch canopy slab of a 2 storey semi-detached house collapsed. The canopy slab failed at the joint to the supporting 2nd storey beam.

Key triggering factor:

- Mainly due to insufficient rebar anchorage of canopy slab into the supporting beam, which is critical in providing the necessary tension capacity for the cantilever car porch.
- Instead of full anchorage with rebar bent 90 degrees vertically into the supporting beam, the rebar was found to be horizontally anchored into the supporting beam.



Lesson Learnt

Cantilever member collapse


RC gutter detached partially from the roof of 4 storey school after structural work completion.

Key triggering factor:

- Inadequate tension reinforcement for additional imposed load when the gutter was filled with water. No design calculation of the gutter.

Lesson learnt:

- Importance of site supervision and reinforcement detailing, especially in cantilever member where the tension rebar has to be adequately anchored into supporting member to provide the necessary bending moment resistance.



Lesson Learnt

Party wall collapse

There were a number of incidents involving the collapse of party wall. The shared party wall between houses made of brick was not designed to resist any lateral forces.

Key triggering factor:

- Incidents typically occurred during concreting of the proposed RC wall that abuts the existing party wall. Hydrostatic pressure from wet concrete exerted lateral force on the party wall that may cause collapse.



Lesson Learnt

Party wall collapse

3-storey shophouse collapsed due to hacking of existing party wall to partially embed new columns and beams.

Key triggering factor:

- The common party wall was weakened as a result of chasing of the existing party wall.
- The timber floor joists were also removed without any temporary bracings added, further compromising the overall stability of party wall.





Lesson Learnt

Party wall collapse

Lesson learnt:

- Independent formwork system to be adopted in order not to exert pressure directly onto the non-structural party wall.
- Rate of discharge during concreting is to be controlled.
- Location and condition of existing party wall is to be investigated beforehand to ensure that the wall stability is not undermined during construction.
- No embedment of any structural elements within the existing party wall.



Guides to Improve Safety

Circular on format of structural plan submission

Circular issued on the format of submission for structural plans to provide a systematic listing of the structural elements to be identified for design check in the submission.

Annex B provides a guide on what could be included in design calculations which helps to clearly demonstrate the design of structural elements in a building.

Summary of Structural Elements Sheet

AC should ensure that he has checked all the key structural elements.

S/N	Type of structural elements*	Element markings in structural plan	QP		AC ¹	
			Element markings ³	Page numbers	Element markings ³	Page numbers
1	Footing	F1 to F4, F4a, F5 to F7	Same as plan	5-15	Same as plan	5 – 18
2	Level 1 Beams	1B1 to 1B10	A-1 to A-10	16-30	Same as plan	19 - 39
3	Level 2	2B1 to 2B5	A-11 to A-20	Refer to	Same as	40 – 60

Grouping of Structural Elements Sheet

S/N	Type of structural elements*	Element markings in structural plan	Designed structural elements that are similar	Remarks
1	Beam or N.A.	3B1, 3B2, 3B3, 3B4, 3B5 or N.A.	2B1, 2B2, 2B3, 2B4, 2B5 or [to indicate N.A. if there is no grouping in the design]	Typical floor

* All structural elements in the project to be designed/checked, e.g. piles/ earth retaining structures/ retaining walls/ columns/ walls/ beams/ slabs/staircase/barrier.

Our ref : APPBCA-2019-07
Date : 05/07/2019

Building Engineering Group (#12-01)
Tel : 1800 342 5222

See Distribution List

Dear Sir/Madam,

JOINT BCA / ACES / IES CIRCULAR 2019

GUIDE ON THE FORMAT OF SUBMISSION FOR STRUCTURAL PLANS

Objective

This circular aims to provide a guide on the format of structural plan submissions for Qualified Persons (QPs) and Accredited Checkers (ACs).

Background

Regulation 9 of the Building Control Regulations 2003 sets out the particulars to be shown on detailed structural plans and design calculations. In collaboration with ACES/IES, BCA has developed a guide on the format of structural plan submissions.

Guide on Format of Submission

The guide (refer Annexes A1, A2 and B) has been developed based on industry's comments and good practices from plan submissions. The templates in Annexes A1 and A2 provide a systematic listing of the structural elements for QPs and ACs to identify the structural elements designed/checked in their submissions. Annex B provides a guide on what could be included in design calculations which helps to clearly demonstrate the design of structural elements in a building.

Separation of Annex A1 to list the structural elements designed and checked. ACs are advised to use the recommended design workflow involving data analysis and design model and the BIM model as given in Annex A2 to allow for a more automated process of listing out the summary of structural elements. ACs are encouraged to be organising briefing sessions to share on the proposed format of submission and the recommended design workflow. More details will be provided via Corenet at the next meeting.

In line with the contents and objective of this circular, ACs continue to have a non-attendance fee under Regulation 7 of Building Control (AC and ACO) Regulations to review the design of building works and perform their original calculations.

Please refer to the contents of this letter to your members.

Guides to Improve Safety

Guide for site supervision plan

Guidebook for site supervision plan sets out the principles, requirements and operation of site supervision with risk based inspection regime to take into account the varying risk of different type of works.

The guide provides comprehensive site supervision plan for small-scale and large building works, with a list of supervision checklist, material test, site record template and recommended good site practices.



Guide Book for Site Supervision Plan

Jointly published by **BCA, IES & ACES**

3. Record of Supervision works (to be updated regularly after completion of each project)

S/No	Project Ref. No	Scope of supervision (superstructure / ERSS / demolition / barrier / Cladding)	Date of Permit Issuance (DDMMYY)	Project Sum (\$ Million)	Type of Supervision (Full time/ Immediate)	Start Date of works (DDMMYY)	Endorsement by QP (to be endorsed within 3 days of start of work)	Date of Completion of Supervision works (DDMMYY)	Endorsement by QP (to be endorsed within 3 days of completion of works)

List of Structural Non-Conformances Annex 6: List of NCR

Project Reference No : _____

Project Title : _____

Qualified Person (Supervision):

S/N	Description of Structural Non-Conformance	Date	Notify QP? Yes/No (Date)	QP's Instruction	Follow-up action / rectification	Date of Closure (Inspection and clearance by Supervisor)	Name & Signature of Supervisor

Guides to Improve Safety

Circular on post-installed anchors

Circular issued on post-installed anchors to consider safe selection and installation of post-installed anchors for use in concrete.

Measures to be provided to ensure that the anchors meet the overall design requirement: selection of suitable anchors, corrosion resistance (stainless steel material), preference to adopt cast-in-place anchors over post-installed anchors, sufficient anchorage depth.

of stainless steel material. Furthermore, QPs should be mindful that the required embedment depth for the anchors should be measured from the base material. Any plaster layer should be removed prior to installing the anchors and this requirement should be clearly indicated in the structural plans.

1 Oct 2014

See **Distribution**

Dear Sir/Madam

BS 8539 - STANDARD ON THE USE OF POST-INSTALLED ANCHORS FOR STRUCTURES REQUIRING PLAN APPROVAL

Objective

This circular is to inform the industry on the standard to be complied with when using post-installed anchors for structures requiring plan approval under the Building Control Act.

Background

2 The performance of post-installed anchors is influenced by many factors such as edge distance, spacing, quality and track record of anchors, and particularly, quality of installation. If the anchors are not selected and installed correctly, they might not have the capability to resist the intended loads. Therefore, where possible, cast-in-place anchors should be the preferred option over post-installed anchors.

3 However, if post-installed anchors are to be used, Qualified Persons (QPs) and Builders should follow the recommendations given in **BS 8539 "Code of practice for the selection and installation of post-installed anchors in concrete and masonry"**.

Post-installed anchors for structures requiring plan approval

selection and installation of by providing measures to be in requirements.

es the risk of anchor corrosion hors to be of stainless steel ons require the anchors to be

Guides to Improve Safety

Circular on robustness check

Circulars issued on robustness of building to consider the robustness requirements in the design to prevent disproportionate or progressive collapse.

of vertical structural elements, design of key and bridging elements. **We, therefore, would like to remind structural Qualified Persons (QPs) and Accredited Checkers to give due considerations to the robustness requirements in their designs to ensure that buildings are robust and stable so that, in the event of misuse or accident, disproportionate or progressive collapse can be avoided.**

catastrophic as they are likely to result in disproportionate collapse. **Therefore, the use of cantilevered or multiple level transfer structures in buildings should be avoided wherever possible.** A simple structural system with direct load path not only enhances

02 July 2012

See Distribution List

Dear Sir/Madam

ROBUSTNESS OF BUILDINGS

BCA has observed an increasing number of buildings being built with complex structural layout and systems, such as inclined or curve columns, and cantilevered or multiple levels of transfer structures. Such complex structural layout could have substantial impact on the building robustness and may lead to disproportionate collapse (i.e. collapse of a small area leading to collapse of major parts of the structure). In addition, such complex structures are also more difficult to built and pose higher safety risks during construction. To enhance the robustness of buildings, we would like to highlight some design requirements in the building codes and provide guidelines on the use of transfer structures.

Robustness Requirements

Several robustness requirements are set out in the standards for concrete and steel Part 1 (Code of Practice for Structural Use of Steel) and Part 2 (Code of Practice for Structural Use of Concrete). Structures should be planned and designed so that they are able to resist the effects of accidents. In particular, situations where the failure of a single element could lead to the collapse of a large area of a structure or failure of single elements should be avoided. In general, a careful check has to be made of the structural layout for the safe transfer of loads. Vertical ties should be provided to maintain the integrity of the structure in the event of a major collapse of building if localised failure occurs. Design should include the consideration for the notional removal of columns, beams and bridging elements. We, therefore, would like to remind structural Qualified Persons (QPs) and Accredited Checkers to give due considerations to the robustness requirements in their designs to ensure that buildings are robust and stable so that, in the event of misuse or accident, disproportionate or progressive collapse can be avoided.

Transfer structures such as cantilevered or multiple levels of transfer structures would have a disproportionate impact on the building. Failure of these structures can lead to disproportionate collapse. Therefore, the use of cantilevered or multiple level transfer structures in buildings should be avoided wherever possible. A simple structural system with direct load path not only enhances the robustness of buildings but also reduces the risk of disproportionate collapse.

Guides to Improve Safety

Circular to ensure structural stability of existing party wall

Circular issued on permit condition to ensure structural stability of existing party/boundary wall when carrying out reconstruction/A&A works.

- a) QPs should investigate the location and condition of the existing party wall and boundary wall and adopt suitable design solution to ensure that the stability of the existing walls will not be undermined during construction;
- b) QPs should not embed any structural elements within the existing party wall or boundary wall;
- c) QP should also avoid placing large and continuous structural elements abutting the existing party wall and boundary wall. If this cannot be avoided, the design should ensure that there will not be any forces (lateral and vertical) being transmitted to the existing walls;
- d) During construction, the Builder should not impose any lateral force on the existing party wall and boundary wall;
- e) If concreting works are to be carried out abutting existing party wall and boundary wall, the Builder should provide suitable formwork system to ensure that lateral load from the formwork (due to the wet concrete) is not transmitted onto the existing party wall and boundary wall.

1 Feb 2016

See **Distribution**

Dear Sir/Madam

PERMIT TO CARRY OUT STRUCTURAL WORKS – NEW CONDITION TO ENSURE THE STRUCTURAL STABILITY OF EXISTING PARTY WALL AND BOUNDARY WALL

Objective

This circular is to inform the industry of the inclusion of a new condition to the permit to carry out structural works. The new condition aims to ensure the structural stability of existing party wall and boundary wall when carrying out reconstruction or alterations & additions works.

Background

In the past few years, we had observed recurrent incidents involving the collapse of existing party wall and boundary wall during reconstruction or additions & alterations works, especially at landed houses. Over the last 3 years, there were a total of 6 such cases (see Annex A for examples of such incidents). There were also incidences where existing party walls were indiscriminately hacked to embed structural elements. Such activities undermine the stability of the existing wall. All these incidents warrant urgent action from Qualified Persons and Builders to ensure the structural stability of existing party wall and boundary wall.

Measures to be taken

All Qualified Persons and Builders are advised to pay particular attention to ensure that the structural stability of any existing wall (either party wall or boundary wall) is not undermined during reconstruction or additions & alterations works. In particular, the following measures should be taken into consideration when designing and carrying out construction works:

- a) QPs should investigate the location and condition of the existing party wall and boundary wall and adopt suitable design solution to ensure that the stability of the existing walls will not be undermined during construction;

Closing Remarks

The building should have simple structural systems with clear and direct load path provision.

- Early engagement in conceptual and design stage with structural driven initiatives.
- Validation of computer outputs and peer review of design by experienced engineer.

The building must be robust so that it can still perform its intended function even if any of its elements were to be removed or failed.

- Provide a robust structural scheme with adequate redundancy.

The building should be designed for any foreseeable risks, including external actions, taking into consideration of ground condition.

- Assess the impact of construction to the safety of nearby buildings.

Thank you



@BCASingapore

